

Under Review Notification

Raised By: Scott Cameron

Product #: RB T103225-119

Date: Oct 11 2017

Product Name: CLAMP ASSY

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise Customers	Stop Production	Re-Work Stock	IPP Under Review	Product Specifications Under Review ("Bluefiles")		
RB T103225-119	RB T103225-119 Rev B	Y	Y	N	Y	N	Y	N	17-705	Stop production / Stop ship / Quarantine Inventory

Description of Issue:

RB T103225-119 incorporates OEM engineering order EO 212APA82.
 OEM later cancelled that EO, but current RB T103225-119 has those changes still incorporated.
 That OEM change breaks compatibility with aircraft this tool is used on, as reported both by customer and by Eagle.

RB T103225-119 needs to be updated to reverse changes made by OEM EO 212APA82.
 DART NCR17-6646 / ECN 17-705

Distribution:

VP Operations Director of Operations Director Quality Assurance Director of Engineering	Chief Engineer Engineering Project Managers Engineering Clerk Customer Support Manager	Production Engineers Production Planners Purchasing Manager Technical Support	Product Manager - Solutions Provider
--	---	--	--------------------------------------